EXHIBIT BB

Pacific Grass & Electric 00175-WHA Document 962-28 pivi File of 01 61 0/19 Page 2 of 3

Vegetation Management Work Request NPNB1012335

Oct 30, 2012

0009-9671 PUEBLO 1104-1 Circuit: PUEBLO 1104 #0043291104

SSD Routing #: 910 Contractor: Davey

> Contract: ZS4335009F Work Type: Distribution Acct Type: Maintenance

Total Loc # 38

General Comments:

Address	lum: 18					City		1	Quad Map	Thom	as Guid	e Area		Inspection Dat	e / Time
	TLAS PEAK R	D				NAPA	Ą		JJ-40	T-410		17-4		10/3/12 3:06 PM	
XStreet			Group			Cour	_		Loc Rt:	U-Bld		Insp		Inspection Cor	
						NAPA		1	240	No		mgmv		Davey RG	
Locatio	n Directions								Loc Lat/Lon				er Name #1	Customer Pho	ne #1
5TH SP RD	NW/O/POLE	#193 NXT RD @ MM	I-7.13;POLE	#197	ТОР	OLE#1	198 AL	ONG.	38.41356	2 / -122.24	18458	SAVINO	PANTOVA	707-483-3024	
Alerts Notify Fi	irst Traffic Issu	ue						:	Struct1	Struc	t2		er Name #2	Customer Phot	ne #2
SRA		Tag Number	Tag Type	2		Pack	et Pro	ject#	SSD#:	-				NTW Number	
Yes						0009	-9671		709						
Loc Co.	omments:	TT 48HR CALL F	OR APPOIN	ITME	NT. F	PI CALI	L FIRS	T FOR GA	TE ACCESS	MIKE SA	BOLSKI	OWNER.			
Locatio	on Summary:	Units: 7	Notific	ation:	1										
								<				Complete	ed		>
Crew 1	Tree - Species	Trim Type	Priority	Est Hf	dbh	HV Clr	Est Otv	Date	Qty	T&M	ОТ	Hrs		Ву	TI
LA (Coast Live O	ak TopDirecti	Routine	30	10	12	1	11/9/12	2 1	TR	0		JM		1
Com:															
Tline:			Owner: Co	ounty				Clearance	e: 12						
	/pe: None	VELB Area: No	Tree Lat. 38.41358	/Lon:		405		Worked F							
	om: 0.1 SPN;	VELB Area: No IN GROUP. PNT	Tree Lat	/Lon:		405		Worked F	Reason: Comments:						
Tree Co Psc Co Alerts:	om: 0.1 SPN; om:	IN GROUP. PNT	Tree Lat. 38.41358	/Lon: 37/-12	2.248		4	Worked R	Comments:	TR	0		JM		1
Tree Co Psc Co Alerts:	om: 0.1 SPN; om:		Tree Lat	/Lon:	2.248	12	1	Worked F	Comments:	TR	0		JM		1
Tree Co Psc Co Alerts: LA (Com:	om: 0.1 SPN; om:	IN GROUP. PNT	Tree Lat. 38.41358	/Lon: 37/-12	2.248		1	Worked R	Comments:	TR	0		JM		1
Tree Co Psc Co Alerts: LA (Com: Tline:	om: 0.1 SPN; om:	IN GROUP. PNT	Routine Owner: Pr	/Lon: 37/-12 28 ivate /Lon:	13	12	1	Worked C	comments:	TR	0		JM		1
Tree Co Psc Co Alerts: LA (Com: Tline:	om: 0.1 SPN; om: Coast Live O /pe: None	IN GROUP. PNT ak TopDirecti	Routine Owner: Pr	/Lon: 37/-12 28 ivate /Lon:	13	12	1	Worked C 11/9/12 Clearance Worked R	comments:	TR	0		JM		1
Tree Co Psc Con: LA C Com: Tline: Wire Ty Tree Co Psc Co Alerts:	om: 0.1 SPN; om: Coast Live O /pe: None	IN GROUP. PNT ak TopDirecti VELB Area: No	Routine Owner: Pr	/Lon: 37/-12 28 ivate /Lon:	13	12	1	Worked C 11/9/12 Clearance Worked R	e: 12 Reason:	TR	0		JM		
Tree Co Psc Con: LA C Com: Tline: Wire Ty Tree Co Psc Co Alerts:	om: 0.1 SPN; om: Coast Live O /pe: None om: 0.25 SPN	IN GROUP. PNT ak TopDirecti VELB Area: No	Routine Owner: Pr Tree Lat 38.41355	28 ivate /Lon:	13	12		Worked Control of the	e: 12 Reason:						
Tree Co Psc Co Alerts: LA (Com: Tiline: Wire Ty Tree Co Psc Co Alerts:	om: 0.1 SPN; om: Coast Live O /pe: None om: 0.25 SPN	IN GROUP. PNT ak TopDirecti VELB Area: No	Routine Owner: Pr Tree Lat 38.41355	28 ivate //Lon:	13	12		Worked Control of the	comments: 2 1 e: 12 Reason: Comments:						
Tree Cores Com: Tine: Wire Ty Tree Cores C	om: 0.1 SPN; om: Coast Live O /pe: None om: 0.25 SPN	IN GROUP. PNT ak TopDirecti VELB Area: No	Routine Owner: Pr Tree Lat 38.41355	/Lon: 28 ivate /Lon: 28 ivate/Lon:	13	12		Worked Control of the	e: 12 Reason: 2 1 e: 12 Reason:						1

Alerts:

Pacific Grasses 3 Electric 00175-WHA Document 962-28 Division Management Circuit: PUEBLO 1104 #0043291104

Vegetation Management
Work Request NPNB1012335

Oct 30, 2012

0009-9671 PUEBLO 1104-1 SSD Routing #: 910

Contractor: Davey

Contract: ZS4335009F Work Type: Distribution Acct Type: Maintenance

Total Loc # 38

General Comments:

ation						CALIFORNIA I			200	1 22			Top		- m-	a granes
Addre		70				City				l Map	200 2000	as Guid	S. C. Carrier		Inspection Da	
	ATLAS PEAK F	KD.	In-	C			_		JJ-40		T-410-C6		17-4		10/3/12 3:06 PM	
XStre	et		Group			Coul			Loc F	κτ:	U-Bld		Insp		Inspection Co	mpany
1 0	lion Direction					NAP	Α .		240	_at/Lon	No		mqmv	r Nom - 44	Davey RG	nna 44
	tion Directions	s E#193 NXT RD @ MN	1 7 12 DOLE	#1077	TO D	OLE#4	108 11				/ -122.24	9.459		PANTOVA	Customer Pho 707-483-3024	one #1
RD	SF INVIOLED	-#193 NX1 KD @ WIN	1-7.13,FOLL	+131	IOF	OLL#	190 AL	ONG	30	0.413302	1-122.24	0430	SAVIIVO	FANTOVA	707-403-3024	
Alerts	s First Traffic Iss	sue							Struc	:t1	Struct	2		er Name #2	Customer Pho 707-224-6565	one #2
SRA		Tag Number	Tag Type			Pack	et Pro	ject#	SSD	#:					NTW Number	
Yes			3 7				-9671		709							
Loc (Comments:	TT 48HR CALL F	OR APPOIN	TMEN	IT. P	CAL	L FIRS	ST FOR GA	ATE A	CCESS.	MIKE SAI	BOLSKI	OWNER.			
Loca	tion Summary	: Units: 7	Notifica	tion:												
				1000000000				<					Complete	·d		>
			Defaulte	Est		HV	Est							-		
Crew	Tree - Species	Trim Type	Priority	Ht	dbh	Clr	Otv	Date	i r	Qty	T&M	ОТ	Hrs	T	Ву	T)
LA	Black Oak	TopDirecti	Routine	27	12	15	1	11/9/1	12	1	TR	0		JM		1
Com:																
Tline:	į.		Owner: Pri	vate				Clearanc	ce: 15							
Wire '	Type: None	VELB Area: No	Tree Lat/I 38.41395		.2485	572		Worked I	Reaso	on:						
Psc C	Com:	STM/ 0.7 SP UNDRL	NS;SPRTS;F	LG.				Worked (Comm	nents:						
Psc (Com: s: Coast Live C		NS;SPRTS;F	FLG. 27	10	12	2	Worked 0		nents:	TR	0		JM		1
Psc C Alerts LA Com:	Com: s: Coast Live C	STM/ 0.7 SP UNDRL	Routine	27	10	12	2	11/9/1	12	2	TR	0		JM		1
Psc (Com: s: Coast Live C	STM/ 0.7 SP UNDRL	Routine Owner: Pri	27 vate	10	12	2		12	2	TR	0		JM		1
LA Com:	Com: s: Coast Live C	STM/ 0.7 SP UNDRL	Routine Owner: Pri	27 vate Lon:			2	11/9/1	12 ce: 12	2	TR	0		JM		1
LA Com: Tline: Wire	Com: Coast Live C Type: None Com: 0.8 SP L Com:	STM/ 0.7 SP UNDRL Dak TopDirecti	Routine Owner: Pri Tree Lat/l 38.41397	27 vate Lon: 5/-122	2.248		2	11/9/1	ce: 12	2 on:	TR	0		JM		
Alerts LA Committee Tiline: Tree Psc C Alerts LA	Com: S: Coast Live C S: Type: None Com: 0.8 SP L Com: S:	STM/ 0.7 SP UNDRL Dak TopDirecti VELB Area: No	Routine Owner: Pri Tree Lat/l 38.41397	27 vate Lon: 5/-122	2.248		2	11/9/1 Clearand Worked I	ce: 12 Reaso	2 on:	TR	0		JM JM		
Alerts LA Com: Tline: Tree Psc C Alerts LA Com:	Com: s: Coast Live C : Type: None Com: 0.8 SP L Com: s: Black Oak :	STM/ 0.7 SP UNDRL Dak TopDirecti VELB Area: No	Routine Owner: Pri Tree Lat/l 38.41397	27 vvate Lon: 5/-122 XTM	2.248	598		11/9/1 Clearanc Worked I Worked C	Reasc Comm	2 on: nents:						1
Alerts LA Committee Tiline: Tree Psc C Alerts LA	Com: s: Coast Live C : Type: None Com: 0.8 SP L Com: s: Black Oak :	STM/ 0.7 SP UNDRL Dak TopDirecti VELB Area: No	Routine Owner: Pri Tree Lat/l 38.41397	27 vate Lon: 5/-122 XTM 48	2.248	598		11/9/1 Clearance Worked I	Reasc Comm	2 on: nents:						
Psc C Alerts LA Com: Tilne: Wire Tree Psc C Alerts LA Com: Tilne:	Com: s: Coast Live C : Type: None Com: 0.8 SP L Com: s: Black Oak :	STM/ 0.7 SP UNDRL Dak TopDirecti VELB Area: No	Routine Owner: Pri Tree Lat/l 38.41397: PNT. 1 SMLL Routine Owner: Countrie Lat/l	27 vvate Lon: 55/-122 XTM 48 unty Lon:	30	12		11/9/1 Clearanc Worked I Worked C	Reasc Comm	2 on: nents:						
Psc C Alerts LA Com: Tline: Wire Tree Psc C Alerts LA Com: Tline: Wire Twee Wire Twe	Com: S: Coast Live C Type: None Com: 0.8 SP L Com: S: Black Oak Type: None	STM/ 0.7 SP UNDRL Dak TopDirecti VELB Area: No UNDRLNS IFO FNC;F	Routine Owner: Privalent Annual Street Company Compan	27 vvate Lon: 55/-122 XTM 48 unty Lon:	30	12		11/9/1 Clearance Worked I Worked G	Comm	2 on: nents:						

Location Num: 19